

EXHIBIT 4

FARM BUREAU PROPERTY & CASUALTY

Broken Bow Claims
The company of choice.
3915 Ave N Ste. A
Kearney, NE 68847
Phone: (308) 234-6173 x3
Fax: (515) 453-3628

Claim #: A121320C01
Workfile ID: 525d620f

Estimate of Record

Written By: ANTHONY SCHALL, 5/5/2015 3:55:57 PM
Adjuster: Schall, Anthony

Insured: DANDEE CONCRETE CONSTRUCTION Owner Policy #: Claim #: A121320C01
Type of Loss: Collision Date of Loss: 05/01/2015 12:00 AM Days to Repair: 0
Point of Impact: 13 Rollover Deductible:

Owner (Claimant):	Inspection Location:	Appraiser Information:	Repair Facility:
Dan Buser PO BOX 2587 KEARNEY, NE 68848-2587 (308) 237-4075 Day	Non Drive-in	anthony.schall@fbfs.com (866) 877-3583 x3	

VEHICLE

Year: 2003	Color:	Int:	License:	Production Date:
Make: CHEV	Body Style:	2D P/U	State:	Odometer: 194417
Model: C1500 4X2 SILVERADO WORK	Engine:	6-4.3L-FI	VIN: 1GCEC14X33Z115363	Condition:

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes

DECOR

Dual Mirrors
Tinted Glass

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel

Message Center
Climate Control

RADIO

AM Radio
FM Radio

Stereo

Search/Seek

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes

SEATS

Cloth Seats

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper
Tool Box (Permanent)